

Archive hall



m² 1200 m $60 \times 20,5$ Ĵm 6,80 IL. Wooden floor 1200 834 180 200 • 1200 1500


Characteristics Air-conditioner Possibility of total blackout Soundproofing Excellent acoustics Sectored light system and with flux regulation Rooms for catering support 2 passenger lifts Rooms for dressing rooms and backoffice Possibility of placing a non-soundproof white curtain on a beam Electric power: see plan

Internet: wireless and 2 fixed access points (see plan)




→ Access

- 🕞 - Beams for curtain



63 A three-phase socket
16 A single-phase socket
Internet socket (RJ45)



0

It is forbidden to apply adhesive or any other fixing system that damages the floor. Please, use paper tape before any other type of tape.

It is forbidden to stick any kind of object on the walls or beams.

!

The maximum capacities of the rooms have been calculated with the greatest use of space in mind, so they may vary depending on the layout chosen.

The suspension of infrastructures, such as truss, lighting, projection, sound systems, and others must always be pre-approved by the Congress Centre.

Be careful when passing heavy materials (pallet trucks, lifting platforms, etc.) over floor boxes.

The facilities must be handed over in the same conditions as before.

